Amendments to the Specification:

Please add the following paragraph after the title and before the "Background of the Invention" Section on page 1:

This application is a Divisional of Application No. 09/989,460 filed November 21, 2001.

Please replace the paragraph starting on page 10, line 14 with the following paragraph.

However, if the user does not still perceive an alarm sound or light in accordance with the sensed signal from the pressure switch B, the load imposed on the driving motor 150 of the vacuum cleaner is further increased. If the load is increased, critical damage by which the driving motor 150 cannot perform its own normal operation may be produced.